



IMPACTPRO® WHITE

# Cleaning & Maintenance Guide

Routine care, initial cleaning and hygienic surface maintenance

|            |                |
|------------|----------------|
| DOCUMENT   | IMP-WH-CM-001  |
| REVISION   | Rev C          |
| ISSUE DATE | 10 August 2026 |

## CLEANING PROCEDURE

### Initial clean after installation

- Allow adhesive and sealant to cure before cleaning.
- Remove protective film only when installation work is complete.
- Clean surfaces with an anti-static solution or anti-static wipes where appropriate to reduce static build-up and dust attraction.

### Routine cleaning

- Use a soft cloth with mild soap or detergent.
- Cleaning water / solution should not exceed 60°C.
- Increase cleaning frequency to suit traffic, contamination risk, healthcare protocols or food-production hygiene requirements.

### Stubborn contamination

- Use a compatible alkaline cleaner with a soft cloth.
- Do not use abrasive pads or aggressive mechanical scouring.
- Avoid unverified solvents or abrasive products that may affect the sheet surface.
- Where hot-water pressure cleaning is approved, maintain at least 600mm between nozzle and sheet surface.

| DO                                                       | DO NOT                                                                     |
|----------------------------------------------------------|----------------------------------------------------------------------------|
| Use soft, non-abrasive cloths and compatible detergents. | Use abrasive pads, wire wool or aggressive mechanical scouring.            |
| Test unfamiliar cleaners in an inconspicuous location.   | Assume all solvents / disinfectants are compatible.                        |
| Follow site-specific hygiene procedures.                 | Direct high-pressure cleaning close to joints, profiles or edges.          |
| Keep cleaning records where required by the facility.    | Exceed the 60°C cleaning-solution guidance without technical confirmation. |