



IMPACTPRO® GLOSS

Cleaning & Maintenance Guide

Routine care for high-gloss hygienic PVCu wall cladding

CLEANING & CARE

Initial clean after installation

- Allow adhesive and sealants to cure fully before wet cleaning.
- Remove protective film carefully. Do not use blades or metal scrapers against the gloss face.
- Remove dust using a clean soft cloth or non-abrasive wipe before applying cleaning solution.
- Wash with warm water and a mild neutral detergent, then rinse and dry with a soft lint-free cloth where a streak-free finish is required.

Routine cleaning

- Use soft cloths, microfibre or other non-abrasive cleaning media.
- Do not use abrasive powders, scouring pads, wire wool or aggressive mechanical scrubbers.
- For stubborn contamination, use a compatible alkaline or specialist cleaner only after confirming suitability on an inconspicuous area.
- Do not exceed 60°C cleaning-solution temperature.
- Where pressure cleaning is appropriate, keep the nozzle well clear of joints and use a minimum distance of approximately 600mm unless project guidance requires more.

Disinfection and chemicals

- Follow the disinfectant manufacturer's dilution and contact-time instructions.
- Test strongly coloured products, solvents, oxidising agents or concentrated cleaners before general use.
- Rinse residues that could dry on the gloss face and leave streaks or deposits.
- Do not mix cleaning chemicals.